MacLellan
Polymers to Industry

Data Sheet	UPS-19500-SPRK Small Pipe Repair Kit

Data Sheet Type	Final
Material Reference	UPS-19500-SPRK
Polymer	
Date Issued	08/11/26

Description

Part of the Thistlebond range of high performance, rapid curing, Emergency Repair Engineering products specifically developed for onsite repairs to small leaking pipes, removing the need to replace pipework and enabling production to continue. A pack containing UPS-19601-PR bandages (5 Pieces) and UPS-19060-SG metal repair compound (1 Piece) that produces a long lasting repair with high physical and mechanical strength. See individual products for technical properties

Purposes

Abrasive Resistance
Acid Resistance
Chemical Resistant
Low Gas Permeability
Oil Resistance
Ozone Resitance
Tear Resistant
Water Resistant
Wear Resistant
Weather Resistance

Important Notes about this Material Data Sheet

This datasheet has been carefully compiled to advise you, our customer, in the best possible way. The information, figures, test values, and data correspond to actual engineering standards and are the result of many years of tests and trials. As individual operating conditions influence the application of each product, the information supplied in this datasheet can only be seen as a rough guideline. In every case it is the sole responsibility of the customer to evaluate his individual requirements, in particular whether the specified properties of our products are sufficient for the intended use. This datasheet is subject to alteration without prior notice. All mentioned values contained herein are guiding values representing long-term experience averages. Please be aware that Test Results for individual Material Batches will only be provided if requested at the time of order and may be subject to additional charges and/or lead times. This Data Sheet supersedes all previous data sheets and any other data previously provided either Verbally, Electronic or Written, with reference to the above Material Grade.